



Attorney Docket No. 0300.1125

cfc

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Daisuke ITO

Application No.: 10/657,193

ATTENTION

Confirmation No.: 1637

CERTIFICATE OF CORRECTION

Filed: September 9, 2003

BRANCH

U.S. Patent No.: 6,998,339

Issued: February 14, 2006

For: METHOD OF FORMING CONDUCTOR WIRING PATTERN

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

**Certificate
MAY 09 2006
of Correction**

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date: May 1, 2006

By: *H. J. Staas*
H. J. Staas
Registration No. 22,010

1201 New York Ave, N.W., 7th Floor
Washington, D.C. 20005
Telephone: (202) 434-1500
Facsimile: (202) 434-1501

MAY 09 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : 6,998,339

DATED : February 14, 2006

INVENTOR(S) : Daisuke ITO

Column 8, Line 4, delete "at" and insert -- of -- therefor.
Column 10, Line 17, after "remaining" insert -- in --.

MAILING ADDRESS OF SENDER:
STAAS & HALSEY LLP
1201 New York Ave., N.W.
7th Floor
Washington, DC 20005

PATENT NO. 6,998,339

No. of add'l copies
@ 50¢ per page

⇒

MAY 09 2006